


# Mendota Collection Replacement Parts


GLW1011SB  
GLW1011MBK




GLW1022SB  
GLW1022MBK




GLW1033SB  
GLW1033MBK



GLC1235SB  
GLC1235MBK



GLC1244SB  
GLC1244MBK




7/18,2025 Rev:0b

## All New Replacement Parts:

No.	Part Number	Description	Used On
1	9199-MBK	ACCESSORY STEM 12 MBK	GLC1235MBK, GLC1244MBK
1	9199-SB	ACCESSORY STEM 12 SB	GLC1235SB, GLC1244SB
2	RPCOV0007MBK	4-3-4 H1/4 COVER MBK	GLW1011MBK, GLW1022MBK, GLW1033MBK, GLC1235MBK, GLC1244MBK
2	RPCOV0007SB	4-3-4 H1/4 COVER SB	GLW1011SB, GLW1022SB, GLW1033SB, GLC1235SB, GLC1244SB
3	RPCPY0034MBK	5 H7/8 CPY BALL 6 STM MBK	GLC1235MBK, GLC1244MBK
3	RPCPY0034SB	5 H7/8 CPY BALL 6 STM SB	GLC1235SB, GLC1244SB
4	RPGLS0067EG	(2-5/8+7-7/8)H4-7/8 OE	GLW1011SB, GLW1022SB, GLW1033SB, GLC1235SB, GLC1244SB, GLW1011MBK, GLW1022MBK, GLW1033MBK, GLC1235MBK, GLC1244MBK
5	RPMTG0048MBK	4-11/16 H9/16 MTG MBK/ 3-8-32 L15MM	GLW1022MBK, GLW1033MBK
5	RPMTG0048SB	4-11/16 H9/16 MTG SB/ 3-8-32 L15MM	GLW1022SB, GLW1033SB
6	RPMTG0055MBK	4-7/16 H9/16 MTG MBK/ 8-32 L15MM	GLW1011MBK
6	RPMTG0055SB	4-7/16 H9/16 MTG SB/ 8-32 L15MM	GLW1011SB
7	RPPKT0070WHT	PARTS BAG FOR MENDOTA	GLW1011SB, GLW1022SB, GLW1033SB, GLC1235SB, GLC1244SB, GLW1011MBK, GLW1022MBK, GLW1033MBK, GLC1235MBK, GLC1244MBK

## Part number & detail:



**GENERATION LIGHTING**